



16.

Memorial Parkway looking south from Hiram Street. Although a pleasing example of its period, this older Federal building (c. 1820) has been isolated by vacant lots and the more recent (c. 1910) commercial building adjacent to it.



17.

Memorial Parkway looking north from Hiram Street. As with all too many of the few more pleasingly designed buildings in the area, the Victorian King block is surrounded by unsympathetically remodelled buildings (e.g., John's) and vacant lots.



18.

Hiram Street looking west from Memorial Parkway. The hodge-podge of routinely designed, deteriorating buildings forms an unfortunate foreground for the historic Reformed Church, which already has the burden of fighting its backdrop.