



4.

Church Street looking west from Neilson Street. This row of routinely designed buildings, dating from the mid-to-late 19th century, have been modified by the addition of commercial facades, yet are basically intact.



5.

View from the Christ Church yard across Neilson Street. The asphalt lots and deteriorated brick and cinderblock buildings create an unattractive landscape.



6.

Neilson Street looking north from Hiram Street. The two buildings remaining in this block are undistinguished brick buildings, dating from the late 19th and early 20th centuries.